



b
a
OFF
OFF
Positioning punching
Install the siding
Fasten the safety rope
N
Fasten the safety rope of the lamp
and connect it to the mains
Hanging board control
head indication position
The probe position and the mounting plate probe
indication position should be consistent up and down