

1.SWITCH OFF MAIN
2.MAKE HOLE PATTERN
3.INSTALL THE BASE PLATE
4.CONNECT LAMP TO THE MAIN
5.DRIVE IN THE SCREWS UNTILL TIGHT
6.SWITCH ON THE MAIN AND LIGHT ON