



1



Accessory

Screw A		AX4
Screw B		BX4
Cross point screwdriver		X1
Hexagon screwdriver		X1

2



AX4

Fix the bottom pole onto base plate

3



Open the box of lamp body

4



Connect the terminals body

5



BX4

Fix the lamp holder with the B screws

6



Close the box by screws

7



Insert the tail of the AC cable into the terminal seat of lamp pole.

8



LAVOV
LIGHTING

info@lavovlighting.com | lavovlighting.com