









1



Accessory


Screw A		AX4
Screw B		BX4
Cross point screwdriver		X1
Hexagon screwdriver		X1

2




Fix the bottom pole onto base plate

3




Open the box of lamp body

4




Connect the terminals body

5




Fix the lamp holder with the B screws

6





Close the box by screws

7



Insert the tail of the AC cable into the terminal seat of lamp pole.

8

LAVOV  
LIGHTING

info@lavovlighting.com | lavovlighting.com