





1



Accessory

Screw A		AX4
Screw B		BX4
Cross point screwdriver		X1
Hexagon screwdriver		X1


2



AX4


Fix the bottom pole onto base plate

3




Open the box of lamp body

4



Connect the terminals body

5



BX4


Fix the lamp holder with the B screws

6




Close the box by screws

7



Insert the tail of the AC cable into the terminal seat of lamp pole.

8



LAVOV
LIGHTING

info@lavovlighting.com | lavovlighting.com