



1



Accessory

|                         |   |     |
|-------------------------|---|-----|
| Screw A                 |    | AX4 |
| Screw B                 |    | BX4 |
| Cross point screwdriver |   | X1  |
| Hexagon screwdriver     |  | X1  |

2



AX4

Fix the bottom pole onto base plate

3



Open the box of lamp body

4



Connect the terminals body

5



BX4

Fix the lamp holder with the B screws

6



Close the box by screws

7



Insert the tail of the AC cable into the terminal seat of lamp pole.

8



LAVOV  
LIGHTING

info@lavovlighting.com | lavovlighting.com