



1



Accessory

| | | |
|-------------------------|---|-----|
| Screw A |  | AX4 |
| Screw B |  | BX4 |
| Cross point screwdriver |  | X1 |
| Hexagon screwdriver |  | X1 |

2



AX4

Fix the bottom pole onto base plate

3



Open the box of lamp body

4



Connect the terminals body

5



BX4

Fix the lamp holder with the B screws

6



Close the box by screws

7



Insert the tail of the AC cable into the terminal seat of lamp pole.

8





LAVOV
LIGHTING

info@lavovlighting.com | lavovlighting.com